

LINE TABLE		
NO.	BEARING	LENGTH
L1	S83°42'57"W	7.20'
L2	N50°32'36"W	20.94'
L3	N11°51'40"E	84.42'
L4	N02°46'37"E	222.16'
L5	N24°34'27"E	16.15'
L6	N07°09'50"E	67.47'
L7	N13°25'18"W	13.20'
L8	N10°46'18"E	207.65'

LINE TABLE		
NO.	BEARING	LENGTH
L9	N10°46'18"E	191.73'
L10	N13°25'18"W	12.98'
L11	N07°09'50"E	69.81'
L12	N24°34'27"E	15.88'
L13	N02°46'37"E	240.10'
L14	N01°06'50"W	40.59'
L15	N74°03'21"W	13.80'
L16	S67°38'46"W	28.90'

CURVE TABLE				
NO.	DELTA	RADIUS	LENGTH	CHORD BEARING
C1	16°27'02"	1849.67'	531.07'	N03°38'09"E
C2	19°48'36"	71.96'	24.88'	S20°39'40"W
C3	72°29'57"	24.47'	30.97'	S36°08'12"E
C4	37°30'26"	52.51'	34.37'	N86°04'50"E

GLENN M. DAY III, ET ALL
DOC. NO. D208367819
O.R.T.C.T.

MARY ANGELYN DAY ENGLERT &
DONALD PAUL ENGLERT
CALLED 2.531 ACRES
VOL. 8990, PG. 1190
D.R.T.C.T.

THOMAS M.
PRESSLEY, ET ALL
CALLED 1.0 ACRES
VOL. 14046, PG. 248
O.R.T.C.T.

RIGHT-OF-WAY
DEDICATION
1.374 ACRES
59,854 SQ. FT.

LOT 1, BLOCK 1
6.1405 ACRES
267,480 SQ. FT.

PART OF A CALLED 28.688 ACRES
RCM WATSON BRANCH PARTNERS, LP
INST. NO. D220192821
O.P.R.T.C.T.

RIGHT-OF-WAY
DEDICATION
1.3741 ACRES
59,854 SQ. FT.

REMAINDER OF A
CALLED 28.688 ACRES
RCM WATSON BRANCH
PARTNERS, LP
INST. NO. D220192821
O.P.R.T.C.T.

REMAINDER OF A
CALLED 28.688 ACRES
RCM WATSON BRANCH
PARTNERS, LP
INST. NO. D220192821
O.P.R.T.C.T.

GLENN M. DAY III, ET ALL
DOC. NO. D208367819
O.R.T.C.T.

LOT 1, BLOCK 1
JALALI RETAIL CENTER
DOC. NO. D209192247
O.R.T.C.T.

LOT 1, BLOCK 1
PRESSLEY HWY ADDITION
VOL. 388-160, PG. 98
P.R.T.C.T.

IMOGENE LOUISE
WREAY LAMBERT
VOL. 5429, PG. 778
D.R.T.C.T.

FINAL PLAT
OVERTURE AT MANSFIELD
LOT 1, BLOCK 1
WATSON BRANCH LANE
RIGHT-OF-WAY DEDICATION
7.5146 ACRES

S. S. CALLANDER SURVEY, ABSTRACT NO. 359
CITY OF MANSFIELD, TARRANT COUNTY, TEXAS
CITY FILE NO. SD#20-046

Kimley»Horn

13455 Noel Road, Two Galleria Office
Tower, Suite 700, Dallas, Texas 75240
FIRM # 10115500
Tel. No. (972) 770-1300
Fax No. (972) 239-3620

Scale	Drawn by	Checked by	Date	Project No.	Sheet No.
1" = 40'	MRW	DJD	OCT. 2020	067771668	1 OF 2




THIS PLAT FILED IN INST. NO. D _____, DATE _____

OWNER:
RCM WATSON BRANCH PARTNERS, LP
909 LAKE CAROLYN PARKWAY, SUITE 150
IRVING, TX 75039
CONTACT: TIMOTHY S. COLTART
PHONE: 469-533-4100

DEVELOPER:
GREYSTAR
600 EAST LAS COLINAS BOULEVARD
IRVING, TX 75039
CONTACT: ANDREW ORD
AORD@GREYSTAR.COM
PHONE: 972-444-2197

SURVEYOR:
KIMLEY-HORN AND ASSOCIATES, INC.
13455 NOEL ROAD
TWO GALLERIA OFFICE TOWER, SUITE 700
DALLAS, TEXAS 75240
CONTACT: JUD MULLINIX
EMAIL: JUD.MULLINIX@KIMLEY-HORN.COM
PHONE: 972-770-1300

ENGINEER:
KIMLEY-HORN AND ASSOCIATES, INC.
13455 NOEL ROAD
TWO GALLERIA OFFICE TOWER, SUITE 700
DALLAS, TEXAS 75240
CONTACT: JUD MULLINIX
EMAIL: JUD.MULLINIX@KIMLEY-HORN.COM
PHONE: 972-770-1300



LINE TYPE LEGEND

	BOUNDARY LINE
	EASEMENT LINE
	BUILDING LINE
	PROPERTY LINE

LEGEND

	IRON ROD FOUND
	P.O.B. POINT OF BEGINNING
	P.O.C. POINT OF COMMENCING

NOTES:

- Bearings and coordinates shown are based on the Texas Coordinate System of 1983, North Central Zone (4202), North American Datum of 1983, coordinates shown hereon are grid coordinates and can be adjusted to surface with a scale factor of 1.00011874676.
- Notice: Selling a portion of any lot in this addition by metes and bounds is a violation of state law and City ordinance and is subject to penalties imposed by law.
- All corners are 5/8" iron rod with red plastic cap stamped "KHA" set unless otherwise noted.
- A mandatory Owner's Association will be responsible for the maintenance of the screening fences, common areas, parks, amenity centers, and landscaping.
- The Owners' Association and associated documents shall be filed in accordance with the City of Mansfield policies. These documents must be reviewed by the City attorney prior to filing the final plat. The documents shall be filed with the final plat at the appropriate county when deemed necessary by the attorney. The documents shall be submitted in a timely manner to allow for a minimum of sixty (60) days review. Failure to submit the documents or incomplete documents may result in delay of construction, acceptance of the subdivision or delay in approval of a building permit. The City does not accept the responsibility for any delays in construction, approval, or acceptance of the subdivision caused by the failure to submit the association documents or the inaccuracy of the documents.

MATCH LINE THIS SHEET

P.O.B.

MATCH LINE THIS SHEET

