


Landscape across from Walnut Plaza








Landscape across from Walnut Plaza



Top picture: the dumpster on the left is totally on the other property.

Bottom picture: shows the narrow opening between the dumpster and the building itself.



Delivery truck cannot go back there because there is no room for them to turn without either hitting the building or the dumpsters.

